






② For those temperature sensor without a terminals and no part code, you can replace them as follows:

In order to reduce the types of temperature sensor wiring customers need to buy, we recommend only buying the temperature sensor harness with the part code Q756086 All use the following method to replace them.

Sensor replacement guidelines			
1) Cut off the damaged head of sensor.		4) Strip off the head of the sensor and connect it.	
2) Strip off the sensor wiring.		5) Wrap the two wires together with insulation tape.	
3) Take out a new sensor to cut the head of sensor. (Spare parts code: Q756086 Its technical specifications apply to all MIDEA refrigerators.		6) Wrap the two wires together.	