









8



Select the configuration code with the left rotating knob



Display blink




9



Press option selection button for 5 sec to store

Display

0 YZ



Press right button for 5 sec to store


10



Rotate function selector clockwise until "OFF" is in display




11




Repeat step 7, 8 and 9 to change to "ON"

Display

ON



12



Rotate function selector clockwise OFF-position to exit test program

