

KIT 533

A 9 PIECE REPAIR KIT

- 715G7801-P01-W06-0H2H
- PLTVGL271XAN1

USED IN:

- LG 32LJ590U

FAULT:

- DEAD - C9118 / FB9101 FAULTY

WHATS IN THE KIT?

- F9901
- FB9101
- Q9101
- D9107
- D9110
- R9109
- U9101
- C9118
- ZD9108

WE RECOMMEND ALL KITS ARE FITTED BY QUALIFIED PERSONEL AND WE CAN ACCEPT NO RESPONSIBILITY FOR LOSS INJURY OR DAMAGE CAUSED BY YOUR USE OF THIS KIT AS A SUCCESSFUL REPAIR DEPENDS ON THE ENGINEERS OWN SKILL AND FAULT FINDING ABILITY.